N WE WAS A STATE OF THE PARTY O
1 = 1/4°/
10101/02/
O D D D D D D D D D D D D D D D D D D D
M N N N N N N N N N N N N N N N N N N N
1 1 / 67
- 0 m 41/64/
コート・レンベン
TO STATE

DUTY ON WHICH ENGAGED: Solo practice, sequences 7 & 8.	COURT OF INQUIRY, INVESTIGATING OFFICER'S REPORT:	CER	
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Pupil pilot moved back on control column too quickly, causing A/C to	D-14 DATE: COMPOSITION:	# 19. :- <u>\$</u>)
stall. Pupil was unable to catch swerve and A/C groundlooped, scraping left wing.	ng RECOMMENDATIONS:)
PRIMARY CAUSE: 25. Inexperience.)
)	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OT	HER VIL)
)
SECONDARY CAUSE OR CONTRIBUTING FACTORS:)
35. Cross winds and gusts. 38. Ground loop. 14. Misuse of controls.		RECORDED BY	DATE)
IT. WISUSE OF COURTORS.		CHECKED BY	DATE
))))