		SURFO LEND CLER	15 0 11 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Challer Wig	140/88 1340/88	Truet (1)	00) (e) e3.5. (e3.6	417 (118 t	146 P	Eggleing.	ST JHO LAND
A/C			FAILUR				ENG	NE	FAIL	JRE	
O.F	UNIT #12 E.F.T.S. COM. Goderich #1 TC	$\frac{\text{SES}}{\text{PLACE}} \frac{\text{OF}}{1/2}$	mile s	outh	of	DATE H.Q.		110	тіме 0 -3 9	1730 -3 6	1 / /5'/
TYPE		No. 3930	6 CRA CAT.	sн С	A	SE X	МE	D	X	NIGHT	M - S C E L
L	N A M E RANK	No.	DUTY	1	NJUF	RIES			SERIC	ous	A □ S □ S □ S □ S □ S □ S □ S □ S □ S □
	Spencer, G.H. LAC				ious.	lу			FATAL	YRULNI	S No
Ш	Liantley, J.T. LAC	R182157	PP	Nil	•						E Z THER
PE OF ENGIN				44.04					CAF SERIA		S O S SPAN
F	TYPE A/F NO. EXTENT RE	PORT SERIAL	DATE		• но	JRS FL	OWN I	3Y PILO)TS		1/8/
	& ENGINE OF DAMAGE FO	ORM No.	DAIL	INST.	NIGHT	ON T	YPE	то	TAL	LAST	STA TAKE
L	T/Moth #3936 Totally					DUAL	SOLO	DUAL		6 MOS.	
GORY	G/Major 85945 Totally T/Moth #1276			-	-	12	9	12	9		A G E O F ST
CATEG	SIGNAL NO & DATE UNIT NO & DATE	E COM. I	No. & DATE		REPOR	:т	Fi	LE	D,	ATE	
ر ا	A. 84 5.5.43	ATURE	OF A	CCID	ENT						

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER'S REPORT:	D.14_#8	
Seq. 6, 12 & 15. NATURE OF ACCIDENT AND STAGE OF FLIGHT: Collided with 1276 at approx. 2000', went into spin, recovered at approx. 150', commenced another spin in opposte direction & crashed	DATE: COMPOSITION:	MA) ()
PRIMARY CAUSE: 26. Collision in the air 21. Collisions Acc	Stressing necessity for all keep a constant watch for also a definite need for Fredieving congestion on material (A) Disciplinary (B) Technical (C) Other (A) Disciplinary (B) Technical (C) Other (B) Disciplinary (B) Disciplinary (B) Technical (C) Other (B) Disciplinary (B) Dis	other a/c. There i R.l field as a means ain aerodrome.	.s
SECONDARY CAUSE OR CONTRIBUTING FACTORS:		RECORDED BY	DATE)
))))))))))))		CHECKED BY	DATE)