C PILOT	OTHERS  AIRFRAME FAILURE												Wiscer Protection
	E.F.T.S.	сом.	C A U S	ACE	<u>F /</u>	CCIDE	NTS	!!			TIME 16		
Prince	Albert	2	No.	M.A.	<del></del>	CRASH		H.Q. F	ME	Tr.	) <b>-43-</b>	NIGHT	1 12 1/28
	/Moth				304	CAT.	1	X			X		
	NAME			No.	DUTY		RIES	IES		SERIOUS			
Hen Dal:	Henry, J.C.		PO LAC	J14687 R191346							FATAL INJURY	אאמרעו	DELL A NEC
A PE O PE											CAR SERIAI		S O S SKI
TYPE A/F	TYPE A/F No. EXTENT OF DAMAG		REP		DAT	е Но		JRS FLOWN BY PI		Y PILC	ILOTS		1 1 1 / 6
T/Moth	4304	_Totel		TIM 140.		INST.	NIGHT	ON T	YPE solo		616	LAST 6 MOS.	1 1 46
G/Major	7562/8545	5 Sligh	tly —			51 -	62	79 4	390 -	147 4	509		I H KY
ш —	NO. & DATE	UNIT No. &	DATE	COM	No. & I	ATE	REPOR	T	FI	L F	l L Da	ATE	

DUTY ON WHICH ENGAGED: Dual instruction circuits and land-	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:
ings.  NATURE OF ACCIDENT AND STAGE OF FLIGHT: Student froze on controls and Inst.	D-14 #74  DATE: 1 1 6 40/1 11 / 1 / 1 / 5 //
unable to move the central column	COMPOSITION: LH/18/11/1/1/
back. Port wheel struck the ground and collapsed.	
)	RECOMMENDATIONS:
)	
) PRIMARY CAUSE: 40. Heavy landing - flying into grou	<del>nd</del>
HEAVY	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  Log book endorsed.
secondary cause or contributing factors: 24. Carelessness	RECORDED BY DATE
V/c. STRAIN (34)	
	CHECKED BY DATE