U		S SIRES IN SIRES OF THE SIRES O	CAS OF AUSTIN		ENGIN ENGIN		
À	CAC	JSES O	F A	CCIDENTS	0.7.5	45	7 / 1200
E O	1 1	Poliof	Jondi	ng field		.4\fine 1515 00-38-70	1 1 / .6. /
TYPE	, <u> </u>	Nο		CRASH	SE ME	DAY NIGHT	1 - 1/28/
	TYPE T/Moth	387	0	CAT. C	x ""	x	
L	N A M E RANI	K No.	DUTY	INJUR	IES	SERIOUS	CO B C ORK
	Shanley, J.H. FO	122743	FI	Nil		FATAL INJURY	W > 65
le:	Clarke, W.E.P LNA	FX9089	9 PP	Nil			
ENGINE						CARD	7 121/37/
БZ						SERIAL No.	
PO.						1	14, 70, 14, 170, 14, 170, 14, 170, 14, 170, 14, 170, 14, 170, 14, 170, 14, 170, 170, 170, 170, 170, 170, 170, 170
ТҮРЕ							1/4 ² /40/
-	I LIFE A/F No EXICINI INI	EPORT SERIAL FORM No.	DATE	HOU	ON TYPE	TOTAL	S CHOLES
Ì	T/Moth 3870 Serious			INST. NIGHT		UAL SOLO 6 MOS.	
┢	G/Major 12969/89416 Nil			51 114	46 600	137 845	10/0/
SORY				1 -	8 2	43 36	
ш	u 						
CAT	A.490 28.5.43	E COM.	No. & D	ATE REPORT	FILE	DATE	

				-			
	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICE	<u>R</u>				
1	Dual Instruction.	OR COMMANDING OFFICER'S REPORT:	D.14-100				
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:)			
	Instructor allowed himself 200 yds.	COMPOSITION: OCO,)			
}	on take-off which was insufficient and he failed to become properly)			
)	airborne before reaching the wire						
)	fence, which he struck with his	RECOMMENDATIONS:					
)	tail plane in a semi-stalled condition.)			
}	PRIMARY CAUSE:)			
)	32. Pilot error.						
))			
)		ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHE	₹)			
)		Personal admonition and log	g book endorsemant.)			
)			"Carelessness")			
))			
j	SECONDARY CAUSE OR CONTRIBUTING FACTORS:			}			
j	ll. Hitting obstructions.	ī	RECORDED BY DATE)			
1							
ì		-	CHECKED BY DATE	٦			