U	DILOT	CTHERS				FAIL		(1) 10 et	LART LIGHT	200 G		the M				
E OF A/					USES OF ACCIDENTS PLACE									Mester /		
TYP	NOTEN A/C TYPE	Oxford		No.	AS835		CRASH	C#4	SE	ме	D		NIGHT	1-80	WERT.	
Ц		NAME	R	ANK	No.	DUTY		טנאו	RIES			SERIC	DUS INJURY	A [[DRACE JRE	
PE OF ENGINE				- 1	15805 8 9 1586418					CARD SERIAL				S A Z BU O'HER O'		
ΤΥ	TYPE A/F				SERIAL No.	DAT	E	Hot		URS FLOWN BY PI					24/54/	
	0xford	AS835	Slight	FORM	NO.		19	NIGHT 5	DUAL 12	9PE 50L0	50 DUAL 87	solo 35	LAST 6 MOS.	1"[⊣]/	Trate of	
GORY	Cheetah	X P.17882	7 & S.Al	79508	Nil		1.2		44~	1.8	0:			G H O H	STATE OF THE STATE	
CATE	SIGNAL NO. & DATE UNIT NO. & DA			ATE	TE COM. No. & [DATE	ATE REPOR		T FILE		DATE]	(1) (H)	

)								
DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER									
Formation flying training.	OR COMMANDING OFFICER'S REPORT: D-14.)								
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE									
After touching down on landing, the A/C started to swing due to cross w	COMPOSITION: LS /////	j								
Pilot was unable to check swing and	1)								
damage was caused to A/C during the ensuing ground loop.)								
) ensuring ground 100p.	RECOMMENDATIONS:)								
)) PRIMARY CAUSE:)								
35. Cross winds and gusts.										
2. Swung.)								
\mathcal{Z}	ACTION TAKEN:) `								
	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER	,								
	NIL	,								
)								
SECONDARY CAUSE OR CONTRIBUTING FACTORS:		,								
38. Ground loop.	RECORDED BY DATE	ì								
	RECORDED BY DATE	,								
R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41	CHECKED BY DATE)								
)								