Q.	PILOT OTHERS	AIRFRAME FAILURE					ENGINE FAILURE 8					
PE OF A		TC PLACE M.A.				ENTS	PATE 11.5.43 TIME 0945 H.Q. FILE 1300-BM.770 SE ME DAY NIGHT G NIGHT G					
` ⊢	A/C TYPE Oxford II	No. BM.770			CRASH CAT. C.5		SE	ме	ĐÁ	X	10101/3	
	NAME RAI	v K	K NO. DUTY			, u l l l E S			SERIOUS		OUS	
PE OF ENGINE	Steyla erts, L.D. LAC	16	53595	595 Nil				SE		CAI	CARD RIAL NO.	
ΤΥF	TYPEA/F EXTENT I		REPORT SERIAL		_	но	URS FLOWN BY PILOTS					
	a engine No. of Damage Oxford #BM.770 Serious	lv No.		DAT	li li	ST. NIGHT	ON TY		TOT	SOLO	6 MOS. THE	
7 7	Cheetah 158623/158555 Nil				24	20	65	46	102	75		
EGO								FIL			ATE TO TO STATE	

DUTY ON WHICH ENGAGED: Local solo precautionary landing	OR COMMANDING OFFICER'S REPORT: D.14 #9
practice at R.1)
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: COMPOSITION: LUC/UTB/
Pupil felt tire burst on take off	COMPOSITION: LVC/L/
from R.1. Inspected u/c after	
lowering in the air, saw burst tire partly off rim of wheel &	
decided to land with wheels up.	RECOMMENDATIONS:
-	,
PRIMARY CAUSE:	,
15. Tire failure	
))
16. OTHERS.	
)	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
16	Nil
3	,
	,
CECONDARY CAUCE OR CONTRIBUTING EXCESS	,
secondary cause or contributing factors: 34. Whools up landing	1
	RECORDED BY DATE
37. TIRE BURST. 3 7	
	CHECKED BY DATE