



PURPOSE OF FLIGHT:

Taxiing out for night flying practice.

NATURE OF ACCIDENT:

A/C 3381 taxiing along taxi strip and was turning around the corner lamp when it ran into A/C 258.

CLASSIFICATION:

~~3. Hitting other aircraft.~~

*COLLISIONS*

SECONDARY OR CONTRIBUTORY FACTORS:

~~24. Carelessness.~~

~~62. Taxiing too fast.~~

TECHNICAL OFFICER'S REPORT:

Nil.

*TCA/...*  
*TCA/...*

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

ACTION TAKEN:

Log book endorsed.