

182 61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT 35 L.F.F.S. Neebawa COM. 2 PLACE M.A. DATE 19-6-43 TIME 1015 H.Q. FILE 1100-51-49

A/C TYPE Tiger Moth Tiger Moth No. 5149 D 3858 CRASH CAT. D1 D1 S.E. X M.E. DAY X NIGHT

COMMAND

TYPE OF A/C

TYPE OF UNIT

CATEGORY

4 2 1 7 4 2 1 1 2 4 1 1 2 4 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL
Williams, E.	Lac.	1802422	PP	MIL. (5149)	No. DATE
Grose, H.P.	Lac.	1587375	PP	MIL. (3853)	No. DATE
					D 14 (REVISED)
					No. CHECKED
					11
					#75

MONTH

ENGINE	ENGINE NUMBER(S)	HOURS FLOWN BY PILOTS					
G/L Major 7693/85548 MIL.	G/L Major 12984/89413 MIL.	INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
		1	1	9	26	9	26
		6	5	23	45	23	45

STAGE OF FLIGHT

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61

PURPOSE OF FLIGHT:

Both pilots taxiing out for take off on solo exercises.

NATURE OF ACCIDENT:

Two pupils while taxiing out to take off were involved in taxiing accident.

TECHNICAL OFFICER'S REPORT:

Nil.

Handwritten notes:
7-2-43
7-2-43

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

3. Hitting other aircraft.

SECONDARY OR CONTRIBUTORY FACTORS:

24. Carelessness.

ACTION TAKEN:

Log book endorsed "gross carelessness", "Carelessness"
Pilots dealt with summarily by C.O. in accordance
with T.C.I.3/16 dated 3-4-43.