

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62
ACCIDENT CLASSIFICATION																																	DATE 13.6.43		TIME 1755		COMMAND																								
UNIT 35 S.F.T.S. No. Battleford		COM. 4		PLACE R.2, Brada			H.Q. FILE 1300-X6961			SE.		ME. X		DAY X		NIGHT		MONTH																																											
A/C TYPE Oxford II			No. X.6961		CRASH CAT. C.10		NO.		DATE		D 14 (REVISED)		NO.		CHECKED		STAGE OF FLIGHT																																												
PERSONNEL Bruen, J.G.			RANK LAC	NUMBER 1563372		DUTY PP	INJURIES Nil		NO. A674		DATE 14.6		NO. 6		CHECKED J		FORCED LANDING																																												
																	TAXIING																																												
																	LANDING																																												
																	TAKEOFF																																												
																	FLIGHT																																												
																	STATRY																																												
																	FATAL																																												
																	INJURY																																												
																	3RD																																												
																	RAF																																												
																	M N																																												
ACCIDENT CLASSIFICATION																																	INST. 14		NIGHT 6		ON TYPE		TOTAL																						
ENGINE Cheetah X A178253/159209			ENGINE NUMBER(S) Slight			SOLO 8		DUAL 22		SOLO 42		DUAL 79		INJURY																																															
CATEGORY																																																													
ACCIDENT CLASSIFICATION																																																													

PURPOSE OF FLIGHT:

Flying training.

S.E. Approaches

NATURE OF ACCIDENT:

Opened throttle to warm up stbd engine but engine failed to respond. Pilot landed A/C in field.

CLASSIFICATION:

32. Pilot error.

SECONDARY OR CONTRIBUTORY FACTORS:

34. Wheels up landing.

25. Inexperience.

TECHNICAL OFFICER'S REPORT:

Nil.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

FB/AOP/PCDE/ES/PM/PC/IL/DO/A

ACTION TAKEN:

Nil.