

192		61		60		59		58		57		56		55		54		53		52		51		50		49		48		47		46		45		44		43		42		41		40		39		38		37		36		35		34		33		32		31		7	
ACCIDENT CLASSIFICATION																																																																	
UNIT 15 E.F.T.S. Regina, Sask.		COM. 4		PLACE 10 1/2 miles N. Main Aerodrome		DATE 11-7-43		TIME 0945		H.Q. FILE 1100-50-57		COMMAND		MONTH		STAGE OF FLIGHT																																																	
A/C TYPE Tiger Moth				NO. 5057		CRASH CAT. C 1		S.E. X		M.E.		DAY X		NIGHT		FORCED LANDING																																																	
PERSONNEL				RANK		NUMBER		DUTY		INJURIES		SIGNAL		NO.		DATE																																																	
Brennagh, J.F.				F/S		R60941		FI		Nil		A65		11-7		D 14 (REVISED)																																																	
Westlake, P.E.				LAC		R191113		PP		Nil		9		CHECKED		36																																																	
ENGINE				ENGINE NUMBER (S)				HOURS FLOWN BY PILOTS								LANDING																																																	
G. Major				7485/85396 Nil				INST.		NIGHT		ON TYPE		TOTAL		TAKE-OFF																																																	
										42		SOLO 495		DUAL 77		SOLO 574		DUAL 140		FLIGHT																																													
																				STAT-BY																																													
																				FATAL																																													
																				INJ.																																													
																				3rd																																													
																				INJURY																																													
																				5th																																													
																				RAF																																													
																				M																																													
ACCIDENT CLASSIFICATION																																																																	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		RAF		M			

PURPOSE OF FLIGHT:

20 hr. test

NATURE OF ACCIDENT:

Pupil throttled back in preparation for spin and engine stopped. Instructor took control, checked cockpit and found nothing to cause failure. Dived to 2000' in attempt to start engine to no avail, force landed successfully. In attempt to takeoff (authorized) mud was thrown by wheels damaging propellor.

TECHNICAL OFFICER'S REPORT:

Nil - Engine idling slowly

FTO/XGM

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~54. Engine failure in the air~~

17. Forced Landing

SECONDARY OR CONTRIBUTORY FACTORS:

~~57. Miscellaneous~~

~~44. Bad Surface~~

26. Engine trouble - 2⁺ accident

ACTION TAKEN:

Nil