



PURPOSE OF FLIGHT:

Armament Training flight

NATURE OF ACCIDENT:

A/C was seen diving and flying low near the scene of the accident. Finally flew low and in the ensuing climb, engine stalled and the A/C spun or dove into the ground from starboard.

TECHNICAL OFFICER'S REPORT:

Nil

*1 LOG/AOC/PO4*

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No. 1070

"A stall at low altitude with insufficient height to recover."

CONCLUSIONS OF A.I.B.

Another case of unauthorized low flying.

CLASSIFICATION:

~~16. Unauthorized low flying or aerobatics.~~

*19. Out of Control 19*

SECONDARY OR CONTRIBUTORY FACTORS:

~~22. Stalling-~~

*42. Unauthorized Low Flying*

ACTION TAKEN:

N.A.