

ACCIDENT CLASSIFICATION

UNIT	19 E.F.T.S. Viriden		COM.	2		PLACE	M.A.		DATE	19-9-43		TIME	1620			
	A/C TYPE	TIGER MOTH 82C TIGER MOTH		NO.	5833 -D 3872		CRASH CAT.	"C"5 "C"2		S.E.	x		M.E.			
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL									
Persons, L.S.		LAC	R221620	PP	Slightly Inj.		NO.	DATE								
McKee, G.H.		LAC	R221832	PP	Uninj.		A.193	20-9								
							D 14 (REVISED)									
							NO.	CHECKED								
							5	<input checked="" type="checkbox"/>								
							#40									
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS												
Gypsy Major		7085/82975 Nil		INST.	NIGHT	ON TYPE		TOTAL								
MK IC		7117/86956 Nil				SOLO	DUAL	SOLO	DUAL							
				-	-	2	15	2	15							

COMMAND MONTH STAGE OF FLIGHT

4
2
1
7
4
2
1
FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STAIRY
FATAL
INJ
3RD
INJURY S

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Routine circuits and landings.

NATURE OF ACCIDENT:

A/c 3872 had landed and almost stopped when a/c 5833 struck upper stbd mainplane, causing a/c 3872 to spin around on ground. A/c 5833 struck the ground, ground looped and caused considerable damage to a/c.

TECHNICAL OFFICER'S REPORT:

Nil LCA/100

LCA/XII

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~5. Collision.~~

6. Collisions.

6

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Pupil to be checked before going solo again.