


61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT 12 E.F.T.S. Goderich	COM. 1	PLACE M.A.	DATE 22-9-43	TIME 1725			
A/C TYPE TIGER MOTH I			CRASH CAT. "D"1	H.Q. FILE 1100-39-32			
PERSONNEL		RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Wilson, R.J.		ALA	67563	PP	Uninj.	No.	DATE
						D 14 (REVISED)	
						No.	CHECKED
						#57	

COMMAND

MONTH

STAGE OF FLIGHT

7
4
2
1
7
4
2
1
FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STRATRY
FATAL
INJ.
3RD
5
RAF
M

TYPE OF A/C
TYPE OF UNIT
CATEGORY

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
Gypsy Major IC 7821/85682 Nil		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
		2	-	8	19	9	19

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Seq. 10,11,16 & 17.

Nil

LH/10/17

NATURE OF ACCIDENT:

Approached for a landing, drifting to right, Levelled off too high and dropped wing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

40. Heavy landing - flying into ground.

SECONDARY OR CONTRIBUTORY FACTORS:

32. Pilot error.

ACTION TAKEN:

39. Flattening out too soon.

Extra duties.