

PURPOSE OF FLIGHT: TECHNICAL OFFICER'S REPORT: Flying practice solo. Nil NATURE OF ACCIDENT: Was carrying out exercise 21. and COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: made approach with half flap and FINDINGS: SUMMARY No. 1500 revs. Another a/c was landing ahead and on left and on a parallel course. Giving this a/c half his attention must have neglected A:S.I. which was showing a dangerously low speed. Opened throttle to increase airspeed and maintain height. Crossed aerodrome boundary judged height to be 40 to 50' and closed throttles. A/C stalled, right wind gropped and nose swung to right as a/c hit ground. 22. Stalling. SECONDARY OR CONTRIBUTORY FACTORS: Heavy landing- flying into ground. ÄČTION TAKEN: 32. Pilot error. Entered on F5011 R. C. A. F. L 20 (REVISED) 7M-4-43 (3202) K. P. 5051 H. Q. 885-L 20