

PURPOSE OF FLIGHT: TECHNICAL OFFICER'S REPORT: )Instructional flying. 10 Ad 350 Ni 1 NATURE OF ACCIDENT: Collision while formation flying. COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: at 5000 ft. above ground. Examination FINDINGS: SUMMARY No. 2132 at scene of crash indicated that CAUSE: Failure of Oxford X6963 to keep station X6963 which had completely disintregated properly. struck ground at angle of 60°. It was CIRCUMSTANCES: "Oxford BM769 and X6963 while noted that emergency release of main flying in No. 2 and 3 positions in echelon stbd. door had not been eperated nor had the collided. Oxford X6963 crashed and Oxford BM769 emergency escape hatch. flew back to base. Remarks of C.O. "I concur with the findings." CONCLUSIONS OF A.I.B. Agree with the findings. CLASSIFICATION: Note: Cpl. Tough to be commended on behaviour 26. Collision in the air in bringing A/C back to base in such condition, altho not publicly as in the COLLISIONS. A/C. majority of cases a pupil would be showing bad judgment in attempting to SECONDARY OR CONTRIBUTORY FACTORS: fly the A/C back in such a condition. ACTION TAKEN Nil R. C. A. F. L 20 (REVISED) 7M-4-43 (3202) K.P. 5051