



PURPOSE OF FLIGHT:

Flying training.

NATURE OF ACCIDENT:

A/C crashed on aerodrome perimeter and burst into flames. Did a gentle turn at about 100' and immediately spun into ground.

CLASSIFICATION:

~~23. Spinning~~

19

OUT. OF CONTROL.

SECONDARY OR CONTRIBUTORY FACTORS:

~~22. Stalling~~

18. Loss of control

TECHNICAL OFFICER'S REPORT:

Awaiting investigation.

110 / 100 / 1950 / CN

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No. 2149

Inexperience on part of pilot, in allowing A/C to lose speed in a turn, whilst approaching to land, resulting in a left hand spin, from which he was unable to recover.

CONCLUSION OF A.I.B.

Agree with findings.

ACTION TAKEN:

Nil