

61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT 12 E.F.T.S. Goderich, Ont.		COM. 1	PLACE 1/2 mile west of the Aerodrome.		DATE 16-11-43	TIME 1215			
A/C TYPE TIGER 10TH I		NO. 3898		CRASH CAT. "A"	S.E. X	M.E. DAY X NIGHT			
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL		
Billington S.E.		ALA	FX582017	PP	Killed		No. A145	DATE 17-11	
							D 14 (REVISED)		
							No. 5	CHECKED <input checked="" type="checkbox"/>	
							#23		
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS					
Gipsy Major		7544/85437 totally		INST.	NIGHT	ON TYPE		TOTAL	
						SOLO	DUAL	SOLO	DUAL
				-	-	4	13	4	13

COMMAND
MONTH
STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STAT RV
FATAL
INJ
INJURY

TYPE OF A/C
TYPE OF UNIT
CATEGORY

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

RAF W N

PURPOSE OF FLIGHT:

Seq. 10,12,13,17.

NATURE OF ACCIDENT:

A/C crashed in lake during heavy snow squall.

TECHNICAL OFFICER'S REPORT:

Nil

1400 / 1000 / 1000 / 1000

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No. 2163

Circumstances

Student caught in heavy snow storm, lost control on turn, crashed into Lake Huron. Student apparently killed on impact.

Cause

Probably had difficulty locating aerodrome because of snow storm.

Conclusions of A.I.B.

Agree.

CLASSIFICATION:

~~19. Bad weather.~~

19. Out of Control

SECONDARY OR CONTRIBUTORY FACTORS:

~~18. Loss of control.~~

ACTION TAKEN:

Nil