

PURPOSE OF FLIGHT: TECHNICAL OFFICER'S REPORT: )Night Navigation cross-country experience. NATURE OF ACCIDENT: A poor approach which resulted in COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: the aircraft striking water in a FINDINGS: SUMMARY No. 2216 steep nose down attitude. with CIRCUMSTANCES: Subject a/c crashed on landing, too much hair speed. broke in two at rear of pilot's and observer's compartment. The forward portion of a/c disappeared the remaining portion overturned. CAUSE: Error in judgment on part of the Captain of the a/c in not deciding to go around again before landing. This error was probably caused by fatigue, as may be inferred from the evidence. PECOMENDATIONS: That all pilots be definitely in structed to go around again before landing when CLASSIFICATION: ) 32 Pilot error night flying in a direction indimating possibility of overshoot. CONCLUSIONS OF A.I.B. Agree with findings. NOTEL The I.O. reported that is is proposed to SECONDARY OR CONTRIBUTORY FACTORS: endorse the log book of F/O MacCallum. 40 Meavy landing ACTION TAKEN: This captain should not have been detailed for the flight in his fatigued condition and under R.C.A.F. L 20 (REVISED) the circumstances his log book should not be 7M-4-43 (3202) K.P. 5051 H. Q. 885-L 20 endoreed.