



PURPOSE OF FLIGHT:

W/T training ex.

TECHNICAL OFFICER'S REPORT:

Small oil leak at rocker box.

NATURE OF ACCIDENT:

Engine throwing oil badly, so pilot executed precautionary landing. The a/c was flown to base after being checked.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

58. Precautionary landings.

SECONDARY OR CONTRIBUTORY FACTORS:

33. Technical defect.

ACTION TAKEN:

Nil