

	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,)
PURPOSE OF FLIGHT:	TECHNICAL OFFICER'S REPORT:)
Flying Training. NATURE OF ACCIDENT:	Backfire in carburettor intake.)
Whilst a/c was being started, port engine back fired and caught fire in the carb. intake and in rear of engine. There was heavy wind at the time but with aid of fire extinguisher and tender, flames were controlled and put out.	COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: FINDINGS: SUMMARY No.)
))
))
CLASSIFICATION:		٠,
57. Miscellaneous.)
))
SECONDARY OR CONTRIBUTORY FACTORS:		}
SECONDART OR CONTRIBUTORY PACTORS:)
1	Nil.)
1)
R. C. A. F. L 20 (REVISED) 7 M.4.43 (3202) K. P. 5051 H. Q. 885-L 20	C. C. LTD. 7084-43	
)