

TECHNICAL OFFICER'S REPORT: PURPOSE OF FLIGHT: Training. NTL NATURE OF ACCIDENT: Pilot departed on routine local COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: reconnaissance flight at 1535 hours FINDINGS: SUMMARY No. 2298 and failed to return. CAUSE: (a) Rapidly deteriorating weather and snow storm causing pilot to become lost. Also icing conditions. (b) Situation was aggravated in that P/O Mitchell did not show good judgement in not returning to base sooner when he saw weather deteriorating, and in methods he adopted subsequently to try and locate base. Recommendations: Filekxmaxleral A copy of daily weather forecast be sent to every station concerned each morning. CLASSIFICATION: Conclusions of A.I.B.: Pilot on local reconnaissance patrol became lost when weather deteriorated sooner than forecast. It is considered pilot's failure to return to base on first signs of bad weather and his SECONDARY OR CONTRIBUTORY FACTORS: failure to climb to sufficient height in order to have ACTION TAKEN: better reception over R/T are contributary factors in this case. NIL R. C. A. F. L 20 (REVISED) 7M-4-43 (3202) K.P. 5051 C. C. LTD. 7084-4 H. Q. 885-L 20