

ACCIDENT CLASSIFICATION

TYPE OF A/C	UNIT 36 S.F.T.S. Penhold		COM. 4	PLACE M.A.		DATE 21-3-44	TIME 1215		
	A/C TYPE OXFORD II OXFORD II		NO. 1507 AS781	CRASH CAT. "C"2 "C"21		H.Q. FILE 1100-15-07			
TYPE OF UNIT	PERSONNEL ROACH, R.R.T.		RANK NZLAC	NUMBER 434682	DUTY PP	INJURIES Uninj.		SIGNAL NO. DATE T.57 21-3	
								D 14 (REVISED)	
CATEGORY	ENGINE Cheetah X		ENGINE NUMBER (S) AS4271/227444 RC787/A171834 Nil AS21353/A157490 RC496/A159617 Nil		HOURS FLOWN BY PILOTS				
					INST.	NIGHT	ON TYPE		TOTAL
						SOLO	DUAL	SOLO	DUAL
						7	3	1	8
								21	50

ACCIDENT CLASSIFICATION

COMMAND  
1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36  
37  
38  
39  
40  
41  
42  
43  
44  
45  
46  
47  
48  
49  
50  
51  
52  
53  
54  
55  
56  
57  
58  
59  
60  
61  
62

MONTH  
1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12

STAGE OF FLIGHT  
FORCED LANDING  
TAXIING  
LANDING  
TAKE-OFF  
FLIGHT  
STAT'RY  
FATAL  
INJURY  
3RD  
5

PURPOSE OF FLIGHT:

Solo day circuits and landings.

TECHNICAL OFFICER'S REPORT:

NIL

*MULTI  
TO R/PRT  
MH/AH*

NATURE OF ACCIDENT:

A/C 1507 was being taxied back to hangars, and in the process it struck another a/c which was parked on tarmac, causing damage to both.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

Hitting other a/c.

9

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Log book endorsed "Carelessness" Awarded 7 days G.C. and privileges suspended for one month.