

ACCIDENT CLASSIFICATION

UNIT 12 E.F.T.S. Goderich	COM. 1	PLACE M.A.	DATE 9-6-44	TIME 0915
A/C TYPE TIGER MOTH		NO. 3954	CRASH CAT. "G"	H.Q. FILE 1100-39-54
		S.E. X	M.E.	DAY X
				NIGHT


PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
BLAKEWAY, A.J.	ALA	606082	PP	Slightly	NO. A246	DATE 10-5
					D 14 (REVISED)	
					NO. 3	CHECKED <input checked="" type="checkbox"/>
					#4	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
Gypsy Major	7638/85506 serious	-	-	8	15	8	15

ACCIDENT CLASSIFICATION

COMMAND
MONTH
STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
FATAL
INJ.
3RD
INJURY



PURPOSE OF FLIGHT:

Seq. 10,11,12,13,16,17,22.

NATURE OF ACCIDENT:

Student doing prolonged sideslip during forced landing practice, allowed a/s to get low, stalled and flicked into ground on recovery.

TECHNICAL OFFICER'S REPORT:

LOC/AOC/PSF/A/B
NIL

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~32. Pilot error.~~

20. Flew into ground.

SECONDARY OR CONTRIBUTORY FACTORS:

40. Other.

ACTION TAKEN:

NIL