

PURPOSE OF FLIGHT:

Pupil's test flight.

NATURE OF ACCIDENT:

Engine stopped dead from cruising
revs. with no prior indication of
impending engine failure. Pilot
executed successful forced landing.

TECHNICAL OFFICER'S REPORT:

Mechanical failure - crank shaft broken

FB/AOP/ES/IM/O/I

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

17. Forced landing.

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine trouble - accident

ACTION TAKEN:

NIL