

MULT PURPOSE OF FLIGHT: TECHNICAL OFFICER'S REPORT: Dartmouth to Greenwood, N.S. NATURE OF ACCIDENT: Aircraft crashed in Lake Gaspereau. COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: SUMMARY No. 2496. FINDINGS: CAUSE: Evidence warrants conclusion that cause of both accidents was the fact that Driva Sodn., suddenly encountered conditions of zero visibility whilst flying over low hilly country. Considerable panic and confusion, resulting in 2 of a/c crashing in the ensuing melee. RECOMMENDATIONS: In view of fact that No. 1 ATT Det. is closed down, the I.O. has no recommendations further than stating, in operation of such scope it would appear advisable to have at least two instructors CLASSIFICATION: present in the air at the same time. 19. Out of Control CONCLUSIONS OF A.I.B.: Agree with findings and recommendations. For Note 1 see Summary 2496. SECONDARY OR CONTRIBUTORY FACTORS: Note 2: The I.O. was also of opinion that the whole ACTION TAKEN: exercise from time a/c left Greenwood until most of them returned, was loosely and inefficiently carried out. R. C. A. F. L 20 (REVISED) Nil C. C. LTD. 20157-44