

PURPOSE OF FLIGHT: TECHNICAL OFFICER'S REPORT: Delivery transportation. Ni 1 NATURE OF ACCIDENT: ) On delivery flight to U.K. became lost COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: between Greenland & Iceland, and has FINDINGS: SUMMARY No. not been heard of since. Obscure. CONCLUSIONS: - Mosquito landed at Greenland after a normal flight. After full briffing on 11th., 6 RAF A/C then at B.W.l., including Mosquito, took off for Iceland, during flight Mosq. was reported Missing.Radio Oper. on KB370 went to W/T 6 min. after take-off.when over B.W.3 reported on R/T that was 10.000 over Stn. No further message was heard from Mosq. except faint 808 . CAUSE: - Weather & inexperience presumed to be joint causes of A/C being missing. CLASSIFICATION: RECOMMENDATIONS: -That delivery of Mosq. a/c be carried out in formation. Consideration be given to the advisability of appointment of a commission or Board of Inquiry to thoroughly investigate and report on: SECONDARY OR CONTRIBUTORY FACTORS: 1st:Problems of Trans-Atlantic flights as it affects ACTION TAKEN: (Mosq. a/c as now equipped. (This would include the taking of evidence from a large number of experienced ferry Mosq. Pilots as well as tech. expervs R. C. A. F. L 20 (REVISED) 2nd: Standard of training given; Mosq. crews. H. Q. 885-L 20 C. C. LTD. 20157-44