



PURPOSE OF FLIGHT:

Scheduled Camera Gun Ex.,

NATURE OF ACCIDENT:

Serious glycol leak cut down pilot's visibility and as he started to return to aerodrome, engine cut out. Forced landed wheels up in snow covered field.

CLASSIFICATION:

17. Forced Landing.

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine Trouble - Accident.

TECHNICAL OFFICER'S REPORT:

External glycol leak - Cracked radiator.

*FB/AOP/ES/GLNK/1/1  
JOK/B*

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

ACTION TAKEN:

Nil