

PURPOSE OF FLIGHT:

Nav. Ex. 10 and Searchlight.

TECHNICAL OFFICER'S REPORT:

Stbd. Tire failure.

LUC/UTB/USM ✓

NATURE OF ACCIDENT:

A/C was seen by the A.C.P. at the end of the runway to make a normal approach and landing. About $\frac{3}{4}$ of the way down the runway, the stbd. tire blew out causing the a/c to swing violently to stbd. Visibility good. New moon.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

2. ~~Swing.~~

SECONDARY OR CONTRIBUTORY FACTORS:

37. Tire Burst.

ACTION TAKEN:

Nil