

ACCIDENT CLASSIFICATION

UNIT 124 Ferry Sqdn. COM. RCAF St. Hubert. 1.		PLACE RCAF Stn. St. Hubert, Que	DATE 1-4-45	TIME 1540
A/C TYPE MOSQUITO		NO. Kall16	H.Q. FILE 1300- Kall16	
		CRASH CAT. "B"	S.E.	M.E.
			DAY	NIGHT
			X	X

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
STIFF, J.A.,	F/O	C85676	P.	Uninj.	NO. A.695	DATE 1-4
SAYLES, D.W.,	F/L	C2707	Pass.	Uninj.	D 14 (REVISED)	
					NO. 1	CHECKED
					1	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				DUAL	SOLO	DUAL	SOLO
Merlin MK 225	P. V344501 Slightly						
Merlin MK 225	S. V344589 Slightly	85	37	5	153	72	813

ACCIDENT CLASSIFICATION


COMMAND
MONTH
STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATUTORY
FATAL
INJ.
INJURY 3rd
INJURY 5th
RAF M

TYPE OF A/C

TYPE OF UNIT

CATEGORY



PURPOSE OF FLIGHT:

Airframe and engine test.

NATURE OF ACCIDENT:

Failure of port engine to restart after feathering, wind not sufficient to compensate for a glide landing at 140 m.p.h. so a/c overran runway and hit ditch.

CLASSIFICATION:

1. Overshot.

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine Trouble - Accident.

TECHNICAL OFFICER'S REPORT:

Nil

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

LO/PSO/ES/PR/M/I

Nil