

Training exercise in Army Co-	COURT OF INQUIRY, INVESTIGATING OFFICER TBG/ANT/PCT/XGS
operation. NATURE OF ACCIDENT AND STAGE OF FLIGHT:	Commanding Officer's Report D.14  DATE: 16-5-40
Aircraft wheels sank into soft mud while taxiing across run- way causing it to nose over.	COMPOSITION: F/L D.M. Smith, Commanding Officer S.A.C
	RECOMMENDATIONS: Taxi slower.
PRIMARY CAUSE:	
Uneven surface of aerodrome under construction.	
	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
ECONDARY CAUSE OR CONTRIBUTING FACTORS:	
Taxing too fast	RECORDED BY DATE
	•