

- 31
- 30
- 29
- 28
- 27
- 26
- 25
- 24
- 23
- 22
- 21
- 20
- 19
- 18
- 17
- 16
- 15
- 14
- 13
- 12
- 11
- 10
- 9
- 8
- 7
- 6
- 5
- 4
- 3
- 2
- 1

TYPE OF A/C	PILOT	OTHERS	AIRFRAME FAILURE				ENGINE FAILURE				
TYPE OF ENGINE	CAUSES OF ACCIDENTS										MISCELLANEOUS
CATEGORY	UNIT No. 5 E.F.T.S.		COM. #4		PLACE		DATE 24-8-40		TIME 1730		HAND-O.
	Lethbridge, Alta.						H.O. FILE 1100-40-86				
	A/C TYPE Tiger Moth		NO. 4086		CRASH CAT. B		SE <input checked="" type="checkbox"/>	ME	DAY <input checked="" type="checkbox"/>	NIGHT	WEATHER
	NAME		RANK		NO.		DUTY		INJURIES		DRKNS.
	McKernan, M.G.A.		LAC		R58834		1P		Uninjured		AL'G SURF.
											OTHER
											UNDT'D
											PRIMARY
											TAXTING
											LANDING
											TAKE-OFF
											FLIGHT
											STATRY
											FATAL
											INJ.
											3RD.
											RAF
											5

- NATURE OF ACCIDENT
- 31
 - 30
 - 29
 - 28
 - 27
 - 26
 - 25
 - 24
 - 23
 - 22
 - 21
 - 20
 - 19
 - 18
 - 17
 - 16
 - 15
 - 14
 - 13
 - 12
 - 11
 - 10
 - 9
 - 8
 - 7
 - 6
 - 5
 - 4
 - 3
 - 2
 - 1

DUTY ON WHICH ENGAGED:

Solo practice (Forced landing)

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

FB/AMNK

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Aircraft forced to land during forced landing practice

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

Pilot states able to move controls only slightly, necessitating forced landing.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY

DATE

CHECKED BY

DATE