

DUTY ON WHICH ENGAGED:

Forced landing practice.

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

ILCO/Pol

Commanding Officer's Report

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Low flying - hit telephone wires

DATE: **6-9-40**

COMPOSITION: **F/L J.C. Fee**

C.O. #4 E.F.T.S. Windsor Mills, P.Q.

RECOMMENDATIONS:

Punishment to be awarded.

Warning to pupil pilots concerning disobedience of

PRIMARY CAUSE: **Disobedience of Station**

Flying Orders.

Flying Orders in that he did fly

Forced landing practice will not be carried out in

lower than 200 feet while practicing/

future by pupil unless accompanied by an instructor

forced landings thus striking some

telephone wires with the propeller

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

of the aircraft. The pupil made an

Above carried out.

approach in a field not authorized

D.14 approved by A.M.T. 30-9-40

by the Chief Instructor of the School.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY

DATE

CHECKED BY

DATE