

DUTY ON WHICH ENGAGED: Flying Instruction. NATURE OF ACCIDENT AND STAGE OF FLIGHT: Engine failure. A/C forced, landed in lake sank to the bottom.	COURTING HAVE TIGATING OFFICER FS/AOP/ES/NK/Z OR COMMANDING OFFICER'S REPORT: Court of Inquiry (D.6) DATE: 17-0-140. COMPOSITION: President- S/L M.M. Hendrick Member - F/0. L. Dawson " - F/0. J.G. Ryrie RECOMMENDATIONS: Strict adherence to Station flying orders.
PRIMARY CAUSE: An error in judgement on the part of the pilot in fly- ing low over glassy water. (This finding was not concurred in by either the A.O.C. "2 T.C., or A.M.O.T.) Word of pilot must be believed in that there was an engine failure causing forced landing. SECONDARY CAUSE OR CONTRIBUTING FACTORS:	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER Court approved by A.M.O.T. with the exception of the findings as to the cause of the accident are not concurred in due to lack of sufficient evidence. 6-1140.
))))))))))))))))))))))	TECORDED BY DATE CHECKED BY DATE DATE DATE DATE DATE