

) j	DUTY ON WHICH ENGAGED: Flying training- Circuit flying. NATURE OF ACCIDENT AND STAGE OF FLIGHT: In a heavy fog, the pilotle lost control of the aircraft and as the ground suddenly appeared an attempt was made to right the A/C. The right wing truck first, and bounced several PRIMARY CAUSE: times. Inexperience on the part of the pilot. He was caght in a fog which closed down on the aerodrome within 19 minutes. He was unable to cope with this contingency.	COURT OF INQUIRY, INVESTIGATING OFFICER TLOC ACCIPS FILT OR COMMANDING OFFICER'S REPORT: Court of Inquiry DATE: 29-9-40 to 3-10-40 COMPOSITION: Flight Lieutenant D.D. Atkinson, pres. Flying Officer H.A. Beer, member Flying Officer J.C. Raymond, member RECOMMENDATIONS: CFI to obtain weather reports from St. Hubert and Megantic. An aircraft should be sent up to ascertain the local conditions within an area circumscribed by a radius of 20 miles from the aerodome. ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER D.6 approved with the exception of the second recommendation above, by A.M.T. 4-10-40.	
	SECONDARY CAUSE OR CONTRIBUTING FACTORS:	RECORDED BY DATE CHECKED BY DATE O COLUMN	