

() <b>, () ) ) ) ) ) ) ) ) ) ) ) )</b>	) ) ) <b>) ) ) ) ) ) ) ) ) ) ) ) ) ) ) ) </b>	つづつ
DUTY ON WHICH ENGAGED: TEST FLIGHT.	COURT OF INQUIRY, INVESTIGATING OFFICER OMPANT	• -
en e	OR COMMANDING OFFICER'S REPORT:	
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	INVESTIGATING OFFICER'S REPORT.  DATE: 21-12-40	
THE PILOT ENDEAVORED TO TAKE OFF IN THE	COMPOSITION:	
USUAL MANNER AND APPARENTLY USED ALL HIS BKILL TO GET THE AIRCRAFT OFF THE	Flt.Lt. Lipton	
GROUND , BUT WITHOUT SUCCESS. SEEING HE COULD NOT GET OFF THE GROUND HE	RECOMMENDATIONS:	
PROCEEDED TO BRING THE A/C TO A STOP BUT BEFORE HE COULD HE RAN INTO SWAMP PRIMARY CAUSE LAND AND DAMAGED THE A/C.	That canvas covers be provided for metal covered aircraft which by reason of lack of hangar space have to remain outside in	
Combination of a frost formation on the airfoils limiting	coldweather.	, .
liefting characteristics and a crusty aerodrome surface which	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
impeded forward motion of the air-craft.		
	· · · · · · · · · · · · · · · · · · ·	
SECONDARY CAUSE OR CONTRIBUTING FACTORS:		
1. Five occupants - too heavy in view of above.	• · · · · · · · · · · · · · · · · · · ·	
2. Aircraft overran boundary of ai drome and went into swamp	PECORDED BY	DATE
	CHECKED BY	DATE
(		) ) )