

())))))))))))))))))
DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
)	OR COMMANDING OFFICER'S REPORT: MA/PEDE
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	Monthly Accident Report.
Airman (AC1) Coulsey swinging	COMPOSITION:
) airscrew gave pilot signal "switch	
off" "throttle wide" and pilot	
repeated signal but turned switches on. When Airman turned airscrew	RECOMMENDATIONS:
) forward engine fired and propellor	Endorsation of Pilot's Log Book -
struck him on the hand.	and disciplinary action taken against
) Carelessness am the part of the pile	Pilot by personal admonition by C.O.
) in not checking position of ignition	
switches before notifying the airman who was swinging the airscrew.	ACTION TAKEN:
)	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
· · · · · · · · · · · · · · · · · · ·	
) SECONDARY CALLES OR CONTRIBUTING PAGEORS	
) SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
) Ignition switches were in the "on	RECORDED BY DATE
) position while engine was being "suc	
)))))))))))-))))))))))))))))