

ALTON ENSAGED: ALTONIAL WAS being started up, puller to running up on ground, majure of accident and stage of rushing. L.A.C. McIntyre while starting up Tiger Moth 5063 was struck on the	DATE: Jamuary COMPOSITION:	5th, 1942 .	restigating Offi "Report"	
right arm by the airscrew.	F/Lt.	J.S. Mason	No. 87127	,
	DECOMMENDATIONS		•	
	RECOMMENDATIONS	•		حج سے آد ایک
			is sufficient of were "on" in the	
PRIMARY CAUSE:			dered that blame	
The Switches were "on" in the	attached to		ISLAC ANSA PISM	, can be
front cockpit, in spite of the	addenner on a			
fact that A.C. Makin states that				
this was not so.	ACTION TAKEN: (A) DISCIPLINARY	(B) Technical (C) Othi	FR .	
•	my bloom ammin	(D) I LONNING (O) O III	LN	
		Nil		
		• • •		
	•			
SECONDARY CAUSE OR CONTRIBUTING FACTORS:				
LAC McIntyre struck on the right				
arm by airscrew.			RECORDED BY	DATE
			CHECKED BY	DATE