

,))))))) 3 3 3 3 3 3 3 3	,,,,,,,,,,,,,, ,,,,,,,,,,,,,,,,,,,,,,	
)	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	
)	N.A.	OR COMMANDING OFFICER'S REPORT: R170	
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:	
)	Aircraft had been trimmed nose	COMPOSITION:	
)	heavy in the course of running up the engine the tail lifted)	
)	resulting in the propeller) [
)	touching the tarmac.	RECOMMENDATIONS:	
)		Nil 3	
)	PRIMARY CAUSE:)	
Ś	Unauthorized handling of aircraft.		
`		9	
<i>)</i>		ACTION TAKEN:	
)		(A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
)		All personnel and starting crew warned in regard to starting engines and trimming devices.	
)		ACI Lyon remanded by C.O.	
))	
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:)	
)	Propeller touched the tarmac.	RECORDED BY DATE	
)		RECORDED DI DATE	
,			
)	R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41	CHECKED BY DATE	
) .			