

DUTY ON WHICH ENGAGED:	COURT OF INCHIEV INVESTIGATING OFFICER
Swinging the airscrew before	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:
take-off.	Investigating Officer's Report
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: 21-5-42
LAC Paterson was swinging the	COMPOSITION:
airscrew and gave the signal for contact. Sgt. Holtsman put the	F.L. D.R.Jacox (C1473) No. 2 F.I.S., Claresholm, Alta
starter switch in the "on" position	
and LAC Paterson swung the airsore	WECOMMENDATIONS: The fact that personnel of this unit
The engine back fired striking	are not familiar with a/c which have to be started by
Paterson across the right hand. PRIMARY CAUSE:	hand has made it difficult to ensure that everyone is
THIMART CAUSE.	thoroughly trained. Closer supervision of training
The part of the second	
Inexperienced propellor swinging	in this respect by the N.C.C.'s in charge of the
on the part of LAC Paterson.	
	in this respect by the N.C.C.'s in charge of the flights is being installed. ACTION TAKEN:
on the part of LAC Paterson.	in this respect by the N.C.C.'s in charge of the flights is being installed.
on the part of LAC Paterson.	in this respect by the N.C.C.'s in charge of the flights is being installed. ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
on the part of LAC Paterson.	in this respect by the N.C.C.'s in charge of the flights is being installed. ACTION TAKEN:
on the part of LAC Paterson.	in this respect by the N.C.C.'s in charge of the flights is being installed. ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
PROP.	in this respect by the N.C.C.'s in charge of the flights is being installed. ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
PROP. SECONDARY CAUSE OR CONTRIBUTING FACTORS:	in this respect by the N.C.C.'s in charge of the flights is being installed. ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER Nil
SECONDARY CAUSE OR CONTRIBUTING FACTORS: Engine back-fired, propellor strike	in this respect by the N.C.C.'s in charge of the flights is being installed. ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER Nil
PROP. SECONDARY CAUSE OR CONTRIBUTING FACTORS:	in this respect by the N.C.C.'s in charge of the flights is being installed. ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER Nil