

, , , , , , , , , , , , , , , , , , , 	
DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
	OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:
A cyclone came up with very little	COMPOSITION:
warning. Three of the A/C were)
lifted and blown through telegraph wires and the fourth blew right ov	
the ground.	RECOMMENDATIONS:
PRIMARY CAUSE:	")
Cycline of such strength as to ren	der
it impossible to hold A/C on groun	d.
	ACTION TAKEN:
	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
	Part of the unit aerodrome is now serviceable, and it is accordingly possible to work from it as a base.
)
)
SECONDARY CAUSE OR CONTRIBUTING FACTORS:)
No hangar accomodation as it was no	
	RECORDED BY DATE
No hangar accomodation as it was no possible to operate from the unit	