

DUTY ON WHICH ENGAGED:

Student instruction.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Forced landed due to engine failure.

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

Engine failed due to valve rocker
bracket holding down studs sheared.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

NIL.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

A/C force landed.

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____