

1	) ) ) ) ) <b>) ) ) ) ) ) ) ) ) ) ) ) ) ) </b>	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	1,,,,	))))))
<b>(</b>	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFI	CFR	
$  \rangle$	Dual instruction on circuits.	OR COMMANDING OFFICER'S REPORT:		
		An aner		
ļ ,	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:	in the Property of the State o	)
)	Engine failed in climbing turn. Ir	SOMPOSITION:		)
)	structor took over control, but the	•		
	engine failed to respond. Due to low altitude pilot turned off gas			)
,	and switches and carried out suc-			
$\rightarrow$	cessful forced landing. A/C was	RECOMMENDATIONS:		)
)	dismantled and brought back to			,
	Aerodrome. PRIMARY CAUSE:			)
<i></i> .	54. Engine failure in the air.			)
)	ore mignio farities in the air.			- '
)				,
. ``		ACTION TAKEN:		)
		(A) DISCIPLINARY (B) TECHNICAL (C)	OTHER	)
)				)
)				1
)				,
	000000000000000000000000000000000000000			)
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:			)
)			RECORDED BY	
)			WECORDED BA	DATE
,				)
)	R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41		CHECKED BY	DATE )
)	) ) ) ) ) <b>) ) ) ) ) ) ) ) ) ) ) ) ) ) </b>	))))))))))	) ) ) ) )	, , , , , ,