

)	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:  D.14	<i>-</i> }
) )	NATURE OF ACCIDENT AND STAGE OF FLIGHT:  Civilian mechanic started a/c engine with no one in cockpit.  A/c jumped chocks & after ground	DATE: COMPOSITION:	)
)	looping by itself, it ran into a building & overturned.	RECOMMENDATIONS:	)
) )	PRIMARY CAUSE: 56. Propellor Swinging		) )
) ) ) ) )		ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  Case referred to civilian manager for disciplinary action.	) ) ) )
)	secondary cause or contributing factors:  2. Hitting obstructions  37. Overturning  24. Carelessness	RECORDED BY DATE	)
);		CHECKED BY DATE  ( ) ) ) ) ) ) ) ) ) ) ) ) ) ) ) ) ) )	) )