

PILOT		OTHERS				AIRFRAME FAILURE				ENGINE FAILURE						
CAUSES OF ACCIDENTS												HAND-O.				
UNIT		COM.		PLACE		DATE		TIME		H.O. FILE		MISCELLANEOUS CAUSES				
Central Flying School, Trenton		1		Inside Hangar, Trenton		21-1-41		2330				INSTS. WEATHER				
A/C TYPE		No.		CRASH CAT.		SE		ME		DAY		NIGHT				
Finch II		4720		Nil		X						X				
NAME			RANK	No.	DUTY	INJURIES				SERIOUS		MISCELLANEOUS CAUSES				
Weenk, H.J.			IAC	R61880	OC	Slightly injured				FATAL	INJURY	AL'G SURF.				
										1		OTHER				
										CARD SERIAL No.		UNDT/D				
												PRIMARY				
												TAXIING				
												LANDING				
												TAKE-OFF				
												FLIGHT				
												STATORY				
												FATAL				
												3RD. INJURY				
TYPE A/F & ENGINE			No.	EXTENT OF DAMAGE	REPORT FORM	SERIAL No.	DATE	HOURS FLOWN BY PILOTS						STAGE OF FLIGHT		
Finch II			4720	Nil				INST.	NIGHT	ON TYPE		TOTAL		LAST 6 MOS.		
Kimer B5			6352/							DUAL	SOLO	DUAL	SOLO			
			1699	Nil												
SIGNAL No. & DATE			UNIT No. & DATE			COM. No. & DATE			REPORT			FILE		DATE		
108			23-1-41			A237			23-1-41							
NATURE OF ACCIDENT																

NIFA

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

MA

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

LAC Weenk was struck by airscrew.

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY

DATE

CHECKED BY

DATE