

了 ? ? ?	DUTY ON WHICH ENGAGED: Practicing forced landings. NATURE OF ACCIDENT AND STAGE OF FLIGHT: The engine failed and wheel landing was made in a snow field.	COURT OF INQUIRY, INVESTIGATING OFFICED FOR APPES/MC/PH/TL OR COMMANDING OFFICER'S REPORT: Commanding Officer's Report DATE: 22-1-41 COMPOSITION: Flight Lieutenant D.J. Thomson.
	PRIMARY CAUSE: The pupill did not keep the motor warm with occasional bursts, and the engine consequently failed.	Had the aircraft been equipped with skiis the accident would not have happened. Pupils are to be impressed with the importance of keeping motor warm, and ff not coming down below 200ft. ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
	SECONDARY CAUSE OR CONTRIBUTING FACTORS: Wheel landing in a snow covered field.	D.14 approved by A.M.T. 4-2-41.
))		CHECKED BY DATE