

DUTY ON WHICH ENGAGED:

SOLO PRACTICE OF SEQUENCE 7 , 15 , 17

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

ENGINE FAILED JUST AFTER TAKE-OFF. PUPIL
MADE SATISFACTORY LANDING WITHOUT DAMAGING
AIRCRAFT MUCH.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT: *OEM/ADP/ES/EM/D/O ✓*

COMMANDING OFFICER'S REPORT

DATE: 14-1-41

COMPOSITION:

S/L J.L. BERVEN.

RECOMMENDATIONS:

PRIMARY CAUSE:

SEIZURE OF DISTRIBUTOR BEARING ON MAGNETO
CAUSING FAILURE

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

D.14 APPROVED BY A.M.T. 30-1-41

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____