

/		$\frac{1}{1}$	<b>o</b>
<b>(</b> )	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY-INVESTIGATING OFFICER ZATELLINE	:
)		OR COMMANDING OFFICER'S REPORT:	
)	NATURE OF ACCIDENT AND STACE OF FLIGHT.	Commanding Officer's Report	,
•		PATE: 21-1-41 COMPOSITION: C.J.H. Holms, F/L	フ! マ!
	Occupants of this aircraft were practicing precautionary landings	O. O. H. HOLMB, L/L	<b>)</b> :
,	on aproort. After landing the In-		)
)	structor applied the brakes, which		•
)	COOK HOIG MOLE SUGGESTY CITEM EX-	RECOMMENDATIONS: It is recommended that brakes should	)
)	pected and the aircraft turned over.	should not be used coarsely after landing, but chiefly to fulfill their primary function, i.e.,	<b>&gt;</b>
)	PRIMARY CAUSE:	to be used as a parking brake.	3
)	Mishandling of brakes after landing.		) }
<b>)</b> ,			
	·	ACTION TAKEN:	€
,		(A) DISCIPLINARY (B) TECHNICAL (C) OTHER	)
•			)
)	•	Approved 12-2-41	)
)			<b>)</b>
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:		<b>)</b>
)			5
)		RECORDED BY DATE	,
·			٠.
ر ۱		CHECKED BY DATE	<b>)</b> ;
<i>)</i>		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	)