

	The state of the s		
ور))))))))))
.)	DUTY ON WHICH ENGAGED: Solo practice	COURT OF INQUIRY, INVESTIGATING OFFICER LOPATO PSO)
)	sequence 6p7-9	OR COMMANDING OFFICER'S REPORT:	:)
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	Commanding Officer's Report 1-2-41	
))	Pilot overshot aerodrome on landing	COMPOSITION:)
))	and went outside boundary into soft snow. The soft snow caused	Squadron Leader J.L. Berven.)
)	the aircraft to overturn.	RECOMMENDATIONS:	`\`
)	•	Pupils instructed to be more careful	7
.)	PRIMARY CAUSE:	and open throttle to go around again if)
)	Inexperience,	overshooting.	ار
)			
)		ACTION TAKEN:	
)		(A) DISCIPLINARY (B) TECHNICAL (C) THEN	7
5		Disciplinary action taken.	7
•			. 1
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:)
)	Unpacked snow caused the A/C		1
)	to overturn,	RECORDED BY DATE	7]
)			, 1
)		())))))))))))))))))))