

1		) ) <b>3 3 3 3 3 3</b> 1) ) ) ) ) ) ) ) ) ) )	)
)	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	)
)	Dual instruction	OR COMMANDING OFFICER'S REPORT:  Commanding Officer's Report.	<del>-</del>
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: 12-2-41	
)	1. Taxying too fast. 2. Taxying	COMPOSITION: D.J. Thomson, Flight Lieutenant	)
<b>)</b>	without change of direction. 3.  Making cockpit check while taxying  4. Insufficient lookout.	TMIPET	)
<i>)</i>	Insulliciont lookout.	RECOMMENDATIONS:	7
)		Harsher discipline by operating company regarding in-	
)		structors off duty hours.	7
)	PRIMARY CAUSE:		)
)	Sheer carelessness on part of capable and reliable instructor		<b>)</b> [
)	due to over-fatigue caused by		)
)	not taking sufficient sleep.	ACTION TAKEN:	)
, )	•	Disciplinary action taken as follows: 1. One month	
<b>)</b>		suspension without pay. 2. Reduced to preceeding	
) \		hourly pay. 3. Loss of 3 months seniority. 4. Log	)
)		book endorsed.	)
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:	Approved 4-3-41	)
)			)
)		RECORDED BY DATE	•
)			). )
<u> </u>	) ) ) ) ) ) ) ) ) ) ) ) ) ) ) ) ) ) )	DATE  DATE  DATE  DATE	5