

5	DUITY ON WHICH ENGAGED. Pre-off of the complete	•
)	DUTY ON WHICH ENGAGED: Practicing aerobati	OR COMMANDING OFFICER'S REPORT:
)))))	Practicing inverted flying and propeller stopped. Pilot was unable to get engine started again by diving and then carried out a forced hand-	Commanding Officer's Report. COMPOSITION: 8-2-41 Squadron Leader J.L. Berven. RECOMMENDATIONS: Instructors lectured and shown how to start engine by diving and pulling out sharply.
	•	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER)
))	SECONDARY CAUSE OR CONTRIBUTING FACTORS:) -
))	Pilot did not apply the procedure for restarting the engine while in the air. The deep snow caused	RECORDED BY DATE
)	the aircfaft to overturn.	CHECKED BY DATE)